

# Eckelmann

## Release notes

### Case Controller UA 410 L AC 2<sup>nd</sup> Generation - Firmware V3.03



# Eckelmann

## **Eckelmann AG Business Unit Refrigeration and Building Management Systems**

Berliner Straße 161  
65205 Wiesbaden  
Deutschland

Tel.: +49 611 7103-700  
Fax: +49 611 7103-133

elds-support@eckelmann.de  
www.eckelmann.de

Board of Directors: Dipl.-Ing. Peter Frankenbach (Speaker),  
Dipl.-Wirtsch.-Ing. Philipp Eckelmann, Dr.-Ing. Marco Münchhof


Chairman of the supervisory board: Hubertus G. Krossa

Registration court / registration number: District court Wiesbaden Germany, HRB 12636

Before commissioning and use, please check that this is the latest version of the document. With the publication of a new version of the documentation, all previous versions lose their validity.

Errors and technical modifications are expressly reserved.

The current operating manual and information such as data sheets, more detailed documentation and FAQs are available for you on-line in E°EDP (Eckelmann ° Electronic Documentation Platform) at **[www.eckelmann.de/elds](http://www.eckelmann.de/elds)**



You reach all relevant documents for this component directly using the QR code.

All rights to any use whatever, utilisation, further development, forwarding and creation of copies remain with the Eckelmann AG company.

In particular, neither the contract partners of Eckelmann AG nor other users have the right to distribute or market the IT programs/program parts or modified or edited versions without express written permission. To some extent, names of products/goods or designations are protected for the respective manufacturer (registered trademarks etc.); in any case, no guarantee is assumed for their free availability/permission to use them. The information provided in the description is given independently of any existing patent protection or other third-party rights.

# Eckelmann

## Release notes

### Case Controller UA 410 L AC



A firmware update is **only** to be carried out by trained staff or factory-side by the manufacturer!

The following is a summary of new functions of the current firmware.

### New features compared to previous versions

#### Version V3.03


- Troubleshooting the suppression of alarms via the digital inputs

#### Version V3.02

- Increase of the system stability.

#### Version V3.00

- **2<sup>nd</sup> Generation**
  - New hardware platform UA 410 L AC
  - Processor STM32
  - 9 times DIP switch for controller type setup



- Future software development on this platform