Eckelmann

Release notes

System centre CI 5x00 Firmware V7.12.0



Eckelmann

Eckelmann AG Business Unit Refrigeration and Building Management Systems

Berliner Straße 161 65205 Wiesbaden Deutschland

Tel.: +49 611 7103-700 Fax: +49 611 7103-133

elds-support@eckelmann.de

www.eckelmann.de

Board of Directors:

CEO Dipl.-Wirtsch.-Ing. Philipp Eckelmann, Dipl.-Ing. (FH), Dipl.-Wi.-Ing. (FH) Volker Kugel,

Dr.-Ing. Marco Münchhof

Chairman of the supervisory board: Hubertus G. Krossa

Registration court / registration number: District court Wiesbaden Germany, HRB 12636

Before commissioning and use, please check that this is the latest version of the document. With the publication of a new version of the documentation, all previous versions lose their validity.

Errors and technical modifications are expressly reserved.

The current operating manual and information such as data sheets, more detailed documentation and FAQs are available for you on-line in E°EDP (Eckelmann ° Electronic Documentation Platform) at www.eckelmann.de/elds



You reach all relevant documents for this component directly using the QR code.

All rights to any use whatever, utilisation, further development, forwarding and creation of copies remain with the Eckelmann AG company.

In particular, neither the contract partners of Eckelmann AG nor other users have the right to distribute or market the IT programs/program parts or modified or edited versions without express written permission. To some extent, names of products/goods or designations are protected for the respective manufacturer (registered trademarks etc.); in any case, no guarantee is assumed for their free availability/permission to use them. The information provided in the description is given independently of any existing patent protection or other third-party rights.

Eckelmann

Release notes System centre CI 5x00



A firmware update is **only** to be carried out by trained staff or factory-side by the manufacturer!

The following is a summary of new functions of the current firmware.

New features compared to previous versions

Version 7.12.0

- Integration of Modbus controller Dixell XR75CH.
- Increase of the system stability.

Version 7.10.0

- Increase of the system stability.
- Datapoints from controller UA 401E are available via Modbus RTU (COM4).

Version 7.9.0

- Increase of the system stability.
- Integration of Modbus controller Dixell XR44CH.

Version 7.8.0

- Increase of the system stability.
- Integration of Modbus controller Dixell XR70CX / XR70CH / XR77CX.

Version V7.7.1

• Increase of the system stability.

Version V7.7.0

- Message inputs and special inputs are configurable in the Virtus Control Desk.
- Increase of the system stability.

Version V7.6.1



From this version signaling alarms via analog modem (LDSWin, FAX, SMS) **is not supported** anymore!

Signaling alarms via GSM modem will continue to be supported

- Initial release version.
- Virtus Caelum Apps and Services interface.
- Remote update function.